

METHOD HOME INSPECTIONS

(208) 659-2810

tanner@methodhomeinspector.com





METHOD HOME INSPECTION

106 Village Way 10 Sun Valley, ID 83353

Carissa Connelly AUGUST 5, 2024



Inspector

Tanner Sanders ASHI Certified Home Inspector (208) 659-2810 tanner@methodhomeinspector.com annamathieu@windermere.com



Agent Anna Mathieu Windermere Real Estate (208) 309-1329

TABLE OF CONTENTS

1: General	4
2: Grounds	5
3: Exterior and Foundation	6
4: Roof	7
5: Attic and Roof Structure	8
6: Garage or Carport	9
7: Crawl Space	10
8: Electric	11
9: Fireplaces, Stoves	15
10: Plumbing / Fuel Systems	16
11: Water Heater	18
12: Heating, Ventilation and Air Conditioning (HVAC)	19
13: Kitchen	22
14: Bathroom and Laundry	26
15: Interior, Doors and Windows	29

Method Home Inspections Page 2 of 32

SUMMARY



- 8.7.1 Electric Switches: Not identified
- 8.9.1 Electric Smoke and CO alarms: None CO Alarms
- 13.2.1 Kitchen Counters: Need caulk at gaps
- 13.8.1 Kitchen Range/Cooktop/Oven: Inoperable Cooktop
- 14.2.1 Bathroom and Laundry Counters: Missing Caulk
- 14.6.1 Bathroom and Laundry Toilets: No or bad caulk at base
- 15.3.1 Interior, Doors and Windows Interior Doors: Missing doorstops
- 15.5.1 Interior, Doors and Windows Walls, Ceilings and Fixtures: Minor crack
- 15.5.2 Interior, Doors and Windows Walls, Ceilings and Fixtures: Damage to paint and wall

Method Home Inspections Page 3 of 32

1: GENERAL

		IN	NI	NP	R
1.1	General	Χ			
1.2	Utilities not on	Χ			
1.3	Potential Concerns	Χ			
1.4	What is a home inspection?	Χ			

IN = Inspected NI = Not Inspected NP = Not Present R =

R = Recommendations

Information

1

General: Present General: Client present at end General: Age Source

Client Yes Municipal records or property

listing

General: Number of residential General: Occupied? General: Weather

units inspected. Yes Sunny

General: Temperature General: Type of property

Hot Condo

General: Condo Inspection

The residential dwelling unit was part of a complex that is managed and maintained by a "Homeowners" or "Condo" association. This inspection is limited to a visual evaluation of the systems and components that are located within the dwelling unit inspected. The current condition of "Common Elements" are excluded from this inspection. Such elements include, but are not limited to:

- The building site condition, structural stability, drainage systems and insulation
- All exterior surfaces, materials and structure
- · All roof surfaces, materials and structure
- All attic spaces
- The building foundation, floor substructure and all spaces below, such as basements and/or crawl spaces
- All stairs, landings, porches, hallways, walks and balconies, elevators, utility metering, parking stalls/ports.
- All decks, patios, pools, spas, recreational areas/equipment
- All common areas on the property

Any comments regarding these items in this report have been made as a courtesy only. Consult with the Homeowner's or Condo Association regarding these items.

What is a home inspection?: What is a home inspection?

A home inspection is a non invasive, visual examination of the accessible areas of the property, designed to identify areas of concern within specific systems or components defined by the American Society of Home Inspectors, that are both observed and deemed material by the inspector at the exact date and time of inspection.

Any and all recommendations for repair, replacement, evaluation, as well as maintenance issues found, should be evaluated by the appropriate trades contractors within the client's inspection contingency window or prior to closing, which is contract applicable, in order to obtain proper dollar amount estimates on the cost of said repairs and also because these evaluations could uncover more potential issues than are able to be noted from a purely visual inspection of the property.

This inspection will not reveal every concern or issue that exists, but only those material defects that were observable on the day of the inspection. This inspection is intended to assist in evaluation of the overall condition of the dwelling only. This inspection is not a prediction of future conditions and conditions with the property are subject to change the moment we leave the premises.

Method Home Inspections Page 4 of 32

2: GROUNDS

		IN	NI	NP	R
2.1	General	Χ			
2.2	Soils / Drainage / Landscaping		Χ		
2.3	Driveway			Χ	
2.4	Sidewalks / Patios		Χ		
2.5	Decks / Porches	Χ			
2.6	Stairs		Χ		
2.7	Handrails		Χ		
2.8	Guardrails	Χ			
2.9	Fence		Χ		

IN = Inspected

NI = Not Inspected

NP = Not Present

R = Recommendations

Information

Decks / Porches: ConditionAppeared serviceable

Decks / Porches: MaterialConcrete



Guardrails: ConditionAppeared serviceable

Guardrails: Materials

Metal

Limitations

General

LIMITATIONS

These items are excluded from this inspection: detached buildings or structures, fences and gates, retaining walls, underground drainage systems, swimming pools, spas, hot tubs or saunas, trees, landscaping, ponds, water features, irrigation and playgrounds. Any comments made regarding these items are as a courtesy only.

Method Home Inspections Page 5 of 32

3: EXTERIOR AND FOUNDATION

		IN	NI	NP	R
3.1	General		Χ		
3.2	Exterior Walls / Trim		Χ		
3.3	Foundation		Χ		

Limitations

General

LIMITATIONS

The inspector performs a limited visual inspection of accessible components at the exterior. Items excluded from this inspection include exterior surfaces obscured by vegetation, stored items or debris. Some items such as siding, trim, soffits, vents and windows are sometimes high off the ground, and may be viewed from the ground or from a ladder. This may limit a full evaluation. Some amount of cracking is normal in concrete slabs and foundation walls due to shrinkage and drying.

Method Home Inspections Page 6 of 32

4: ROOF

		IN	NI	NP	R
4.1	General		Χ		
4.2	Shingles / Shakes		Χ		
4.3	Flashings		Χ		
4.4	Gutters / Downspouts / Extensions		Χ		
4.5	Soffits and fascia		Χ		
4.6	Chimney and Flues		Χ		

Limitations

General

LIMITATIONS

The following items or areas are outside the standards of practice and not included in this inspection: areas that could not be traversed or viewed clearly due to lack of access; solar roofing components. Any comments made regarding these items are made as a courtesy only. Note that inspector does not guarantee that leaks have not occurred in the roof surface, skylights or roof penetrations in the past. Regarding roof leaks, only active leaks, visible evidence of possible sources of leaks, and evidence of past leaks observed during the inspection are reported on as part of this inspection. I do not guarantee that leaks will not occur in the future. Total access to all roof and attic spaces during all seasons and during prolonged periods of all types of weather conditions would be needed to do so. Occupants should monitor the condition of roofing materials in the future. For older roofs, recommend that a professional inspect the roof surface, flashings, appurtenances, etc. annually and maintain/repair as might be required. If needed, the roofer should enter attic space(s).

Method Home Inspections Page 7 of 32

5: ATTIC AND ROOF STRUCTURE

		IN	NI	NP	R
5.1	General			Х	
5.2	Access			Χ	
5.3	Roof Structure			Χ	
5.4	Insulation			Χ	
5.5	Ventilation			Χ	
5.6	Moisture Present			Χ	

Limitations

General

LIMITATIONS

The following objects or zones are not included in this inspection: zones that could not be traversed or viewed clearly due to lack of access; zones and components blocked by insulation. Any comments made regarding these items are made as a courtesy only. The inspector does not determine the adequacy of the attic ventilation system. Total access to roof and attic spaces during all seasons and during extended periods of all types of weather conditions would be needed to do so. The inspector is not a licensed engineer and makes no determinations about the adequacy of roof structure components such as trusses, rafters or ceiling beams.

Method Home Inspections Page 8 of 32

6: GARAGE OR CARPORT

		IN	NI	NP	R
6.1	General		Χ		
6.2	Attached Garage-House Door		Χ		
6.3	Vehicle Door		Χ		
6.4	Automatic Opener		Χ		
6.5	Floor		Χ		
6.6	Interior/Walls/Ceilings		Χ		
6.7	Attic access		Χ		
6.8	Garage-house steps		Χ		

Information

Interior/Walls/Ceilings:

Ventilation

Window, Door

Limitations

General

LIMITATIONS

The inspector does not determine the adequacy of firewall ratings.

Method Home Inspections Page 9 of 32

7: CRAWL SPACE

		IN	NI	NP	R
7.1	General			Х	
7.2	Access			Х	
7.3	Floor Substructure			Х	
7.4	Floor Insulation			Χ	
7.5	Vapor Barrier			Χ	
7.6	Ventilation			Χ	

Limitations

General

LIMITATIONS

Structural components and other components that are blocked by under-floor insulation are excluded from this inspection. Examples include, joists, beams, piping, wiring and/ducting. The inspector does not determine if support posts, beams, joists, studs, trusses, etc. are of correct size, spanning or spacing.

Method Home Inspections Page 10 of 32

8: ELECTRIC

		IN	NI	NP	R
8.1	General	Χ			
8.2	Service		Χ		
8.3	Panels	Χ			
8.4	Wiring	Χ			
8.5	Exterior	Χ			
8.6	Receptacles	Χ			
8.7	Switches	Χ			Χ
8.8	Lighting / Fans	Χ			
8.9	Smoke and CO alarms	Χ			Χ

IN = Inspected

NI = Not Inspected

NP = Not Present

R = Recommendations

Information

Panels: Main service panel condition

Appeared serviceable

Panels: Sub-panel(s) condition Appeared serviceable

Panels: Location of MAIN panel Hallway



Panels: Location of MAIN panel

None found

Panels: Location of main disconnect

No single main disconnect. Use all breakers in main service panel

Not determined

Wiring: Branch circuit wiring type Wiring: Solid strand aluminum wiring present None visible

Wiring: Condition Serviceable

Receptacles: GFCI present

Yes

Page 11 of 32 Method Home Inspections

Smoke and CO alarms: CO and smoke alarms installed
Smoke alarm

General: Electric Service Panel





Limitations

General

LIMITATIONS

The following items are not included in this inspection: generator systems, transfer switches, concealed wiring; underground utilities and systems. Note that the inspector does not determine the adequacy of grounding or bonding. The inspector does not operate circuit breakers as part of the inspection. The functionality of power source for and placement of smoke and carbon monoxide alarms is not determined as part of this inspection. Upon taking occupancy, proper operating and placement of smoke and carbon monoxide alarms should be verified and batteries should be changed. The inspector attempts to locate and evaluate all main and sub-panels. However, panels are often concealed. If panels are found after the inspection, a qualified electrician should evaluate and repair if necessary. The inspector attempts to determine the overall electrical service size, but these estimates are not guaranteed because the overall capacity may be diminished by lesser-rated components in the system. Any repairs recommended should be made by a licensed electrician.

Service

LOCKED

The main electrical panel is locked behind a door controlled by the property management company and not able to be accessed.

Method Home Inspections Page 12 of 32



Recommendations

8.7.1 Switches

NOT IDENTIFIED



The inspector operates every accessible switch in the home. Multiple switches appeared to do nothing. The property owner stated these switches were for old lights that have been removed. Recommend having a qualified electrician install new lights or remove the switches if necessary.





Bedroom 1 Master Bedroom

8.9.1 Smoke and CO alarms

NONE - CO ALARMS



Method Home Inspections Page 13 of 32

No permanently installed carbon monoxide alarms were found. This is a potential safety hazard. Some states and/or municipalities require CO alarms to be installed for new construction and/or for homes being sold. Recommend installing approved CO alarms outside of each separate sleeping area in the immediate vicinity of the bedrooms on each level and in accordance with the manufacturer's recommendations.

Method Home Inspections Page 14 of 32

9: FIREPLACES, STOVES

		IN	NI	NP	R
9.1	General			Х	
9.2	Wood-burning fireplace, stove			Х	
9.3	Fireplace			Χ	
9.4	Wood Stove			Х	
9.5	Hearth			Χ	
9.6	Gas-fired fireplace, stove, or log lighter			Х	
9.7	Type B/L Gas Vents			Х	

Limitations

General

LIMITATIONS

The following items are not included in this inspection: coal stoves, gas logs, chimney flues (except where visible). Any comments made regarding these items are as a courtesy only. Note that the inspector does not determine the adequacy of drafting or sizing in fireplace and stove flues, and also does not determine if prefabricated or zero-clearance fireplaces are installed in accordance with the manufacturer's specifications. The inspector does not perform any evaluations that require a pilot light to be lit, and does not light fires. The inspector provides a basic visual examination of a chimney and any associated wood burning device. The National Fire Protection Association has stated that an in-depth Level 2 chimney inspection should be part of every sale or transfer of property with a wood-burning device.

Method Home Inspections Page 15 of 32

10: PLUMBING / FUEL SYSTEMS

		IN	NI	NP	R
10.1	General	Χ			
10.2	Service / Main Line	Χ			
10.3	Supply Lines	Χ			
10.4	Drain and Waste Lines	Χ			
10.5	Venting	Χ			
10.6	Sump Pump			Χ	
10.7	Sewage Ejector Pump			Χ	
10.8	Irrigation		Χ		
10.9	Fuel Systems	Χ			

NI = Not Inspected IN = Inspected NP = Not Present

R = Recommendations

Information

Service / Main Line: Condition

Appeared serviceable

Service / Main Line: Main shut-off Service / Main Line: Type

location Public

inaccessible or none found)

Supply Lines: Condition

Appeared serviceable

Supply Lines: Type

Copper, PEX plastic

Drain and Waste Lines: Drain pipe

condition

Appeared serviceable, Limited

evaluation

Drain and Waste Lines: Waste

pipe condition

Limited evaluation

Drain and Waste Lines: Drain pipe Drain and Waste Lines: Waste

material

PVC

pipe material

Not determined

Venting: Condition

Appeared serviceable

Venting: Vent pipe material

Fuel Systems: Condition

Not determined

Fuel Systems: Location of main

fuel shut-off

Not determined

Fuel Systems: Visible fuel storage

systems

None visible

Limitations

General

LIMITATIONS

Method Home Inspections Page 16 of 32

The following items are not included in this inspection: private/shared wells and related equipment; private sewage disposal systems; hot tubs or spas; main, side and lateral sewer lines; gray water systems; pressure boosting systems; trap primers; incinerating or composting toilets; fire suppression systems; water softeners, conditioners or filtering systems; plumbing components concealed within the foundation or building structure, or in inaccessible areas such as below tubs; underground utilities and systems; overflow drains for tubs and sinks; backflow prevention devices. Any comments made regarding these items are as a courtesy only. It is our recommendation that all homes over 20 years of age have the waste lines inspected using a video scope device to determine if they need repair or replacement. Property owners are usually responsible for repairs to the side sewer and publicly owned lateral lines. Such repairs can be expensive. Note that the inspector does not operate water supply or shut-off valves due to the possibility of valves leaking or breaking when operated. The inspector does not test for lead in the water supply, the water pipes or solder, does not determine if plumbing and fuel lines are adequately sized, and does not determine the existence or condition of underground or above-ground fuel tanks.

Method Home Inspections Page 17 of 32

11: WATER HEATER

		IN	NI	NP	R
11.1	General		Χ		
11.2	Tank Casing		Χ		
11.3	Temp		Χ		
11.4	Water Shut off		Χ		
11.5	TPR drain valve/line		Χ		
11.6	Electric		Χ		
11.7	Burners		Χ		
11.8	Flues		Χ		
11.9	Expansion tank		Χ		

Limitations

General

LIMITATIONS

The inspector does not provide an estimate of remaining life on water heaters, does not determine if water heaters are appropriately sized, or perform any evaluations that require a pilot light to be lit or a shut-off valve to be operated.

General

BLOCKED





Method Home Inspections Page 18 of 32

12: HEATING, VENTILATION AND AIR CONDITIONING (HVAC)

		IN	NI	NP	R
12.1	General	Χ			
12.2	Heating	Χ			
12.3	Electric Heat (not forced air)			Χ	
12.4	Forced Air	Χ			
12.5	Filters	Χ			
12.6	Ducts and Registers	Χ			
12.7	Burners (furnace or boiler)		Χ		
12.8	Combustion Air	Χ			
12.9	Flues	Χ			
12.10	Heat Pump; AC		Χ		
12.11	Normal Controls	Χ			
12.12	Ventilation	Χ			

Information

Heating: Distribution TypeDucts and registers

Forced Air: Condition
Appeared serviceable

Forced Air: BTU's Adequate?

Yes

Heating: Heating TypeForced air, Furnace

Forced Air: Fuel Type
Not determined

Filters: ConditionAppeared serviceable

Heating: Primary heating last

service dateNot determined

Forced Air: LocationNot determined

Filters: Filter locationAt end of air handler

Method Home Inspections Page 19 of 32

Filters: Size 10x20x1



Ducts and Registers: ConditionAppeared serviceable

Combustion Air: TypeVent(s) to exterior

Flues: ConditionAppeared serviceable

Normal Controls: ConditionAppeared serviceable



Heat Pump; AC: ConditionAppeared serviceable

Heat Pump; AC: TypeHeat pump

Method Home Inspections Page 20 of 32

General: HVAC system







Limitations

General

LIMITATIONS

This inspection excludes: humidifiers, dehumidifiers, electronic air filters, solar, coal or wood-fired heat systems, thermostat accuracy, timed functions, heating components concealed within the building, underground utilities, safety devices, and controls due to automatic operation. Comments made on these items are provided as a courtesy only. The inspector doesn't estimate remaining life on heating or cooling system components, determine system size adequacy, test coolant pressure, or perform evaluations requiring specific operational actions, such as lighting a pilot light or operating shut-off valves. Additionally, furnace heat exchanger integrity and leak detection are beyond the scope of this inspection.

Method Home Inspections Page 21 of 32

13: KITCHEN

		IN	NI	NP	R
13.1	General	Χ			
13.2	Counters	Χ			Χ
13.3	Cabinets	Χ			
13.4	Floors	Χ			
13.5	Sinks	Χ			
13.6	Under-Sink Food Disposal	Χ			
13.7	Dishwasher	Χ			
13.8	Range/Cooktop/Oven	Χ			Χ
13.9	Ventilation	Χ			
13.10	Refrigerator	Χ			
13.11	Microwave			Χ	

Information

General: Kitchen



Counters: ConditionAppeared serviceable

Counters: MaterialWood

Kitchen

Cabinets: ConditionAppeared serviceable

Sinks: ConditionAppeared serviceable

Floors: Type or coveringWood or wood products

Under-Sink Food Disposal: Condition

Appeared Serviceable

Floors: ConditionAppeared serviceable

Dishwasher: ConditionAppeared serviceable

Method Home Inspections Page 22 of 32

Dishwasher: BrandWhirlpool



Range/Cooktop/Oven: Condition Range/Cooktop/Oven: Fuel Type
Required repair or replacement Natural gas

Range/Cooktop/Oven: Brand Whirlpool



Ventilation: TypeHood

Refrigerator: ConditionAppeared serviceable

Method Home Inspections Page 23 of 32

Refrigerator: Brand



Limitations

General

LIMITATIONS

This inspection excludes these items: household appliances such as warming ovens, griddles, broilers, trash compactors, ice makers, hot water dispensers and water filters; appliance timers, clocks, cook functions, self-continuous cleaning operations. Any comments made regarding these items are provided as a courtesy only. An estimate of the remaining life of appliances and the adequacy of operation of appliances is excluded from this report.

Recommendations

13.2.1 Counters

NEED CAULK AT GAPS



Gaps were present at the countertop in the kitchen. Water can penetrate this area and cause damage. Recommend installing caulk at gaps now and in the future, when necessary, to prevent water damage.





Kitchen Kitchen

Method Home Inspections Page 24 of 32

13.8.1 Range/Cooktop/Oven



INOPERABLE - COOKTOP

1 cooktop burner was inoperable. The ports may need cleaning. Recommend that a qualified person repair as necessary.



Method Home Inspections Page 25 of 32

14: BATHROOM AND LAUNDRY

		IN	NI	NP	R
14.1	General	Χ			
14.2	Counters	Χ			Χ
14.3	Cabinets	Χ			
14.4	Floors	Χ			
14.5	Sinks	Χ			
14.6	Toilets	Χ			Χ
14.7	Bathtubs	Χ			
14.8	Showers	Χ			
14.9	Ventilation	Χ			
14.10	Laundry	Χ			

IN = Inspected

NI = Not Inspected

NP = Not Present

R = Recommendations

Information

General: Location2nd Floor

Floors: Condition
Appeared serviceable

Toilets: ConditionAppeared serviceable

Ventilation: ConditionAppeared serviceable

Laundry: Gas supply for laundry equipment present

No

Counters: ConditionAppeared serviceable

Floors: Type or covering

Tile

Bathtubs: ConditionAppeared serviceable

Ventilation: Bathroom and laundry ventilation type
Central exhaust fan

Cabinets: ConditionAppeared serviceable

Sinks: Condition

Appeared serviceable

Showers: ConditionAppeared serviceable

Laundry: 240 present

Yes

Method Home Inspections Page 26 of 32

General: Laundry and bathrooms







Laundry Master Bathroom Bathroom 1

Limitations

General

LIMITATIONS

Recommendations

14.2.1 Counters

MISSING CAULK



Gaps were present at the countertops in the master bathroom. Water can penetrate these areas and cause damage. Recommend cleaning the area and installing caulk to prevent water damage.





Master Bathroom

14.6.1 Toilets

NO OR BAD CAULK AT BASE



Method Home Inspections Page 27 of 32

Caulk around the base of the toilet was substandard or deteriorated. Modern standards require caulk to be installed around the entire toilet base where it meets the floor for sanitary reasons. Without it, soiled water can soak into flooring and sub-floor materials if the toilet overflows. Recommend that a qualified person caulk around toilet bases per standard building practices.



Bathroom 1

Method Home Inspections Page 28 of 32

15: INTERIOR, DOORS AND WINDOWS

		IN	NI	NP	R
15.1	General	Χ			
15.2	Exterior Doors	Χ			
15.3	Interior Doors	Χ			Χ
15.4	Windows and Skylights	Χ			
15.5	Walls, Ceilings and Fixtures	Χ			Χ
15.6	Floors	Χ			
15.7	Stairs/Handrails/Gaurdrails			Χ	

IN = Inspected NI = Not Inspected NP = Not Present R = Recommendations

Information

Exterior Doors: Condition

Appeared serviceable

Windows and Skylights:

Condition

Appeared serviceable

Walls, Ceilings and Fixtures:

Condition

Appeared serviceable

Floors: Type or covering

Carpet, Wood or wood products

General: Interior view

Exterior Doors: Exterior door

material

Glass panel, Wood

Windows and Skylights: Window

Wood, Single-hung

Walls, Ceilings and Fixtures: Wall Floors: Condition

type or covering

Drywall

Interior Doors: Condition

Appeared serviceable

Walls, Ceilings and Fixtures:

Ceiling type or covering

Drywall or plaster

Appeared serviceable





Bedroom 1 Living Room

Method Home Inspections Page 29 of 32

Recommendations

15.3.1 Interior Doors

MISSING DOORSTOPS



Doorstops were missing or not working properly in multiple locations. Recommend installing doorstops to prevent wall damage.







Bedroom 1 Bedroom 1 Bathroom 1




15.5.1 Walls, Ceilings and Fixtures

Deficiencies

MINOR CRACK

One interior crack was present. This crack did not appear to be structural. Recommend monitoring in the future for change in appearance. The client may wish to seal and paint the crack for cosmetic purposes.

Method Home Inspections Page 30 of 32



15.5.2 Walls, Ceilings and Fixtures

DAMAGE TO PAINT AND WALL



Damage to paint and wall appears to be due to moisture from the shower. Recommend cleaning the area and repainting to prevent further moisture damage.







Bathroom 1

Method Home Inspections Page 31 of 32



Bathroom 1





Living Room



Master Bathroom

Method Home Inspections Page 32 of 32