

~~All electrical~~

(Plumbing)

5.4 Sinks and faucets - ~~was~~ un-plugged and now draining good

5.7 Bath/Shower -

seal and water running good, neck for the shower adjusted.

6.3 Replace water shut-off valves for the washers.

7.3 Evaluated and repair leak causing leakage pipe in the crawl space.

7.4 Sewage Ejector Pump -

Repaired and tested for sewer gas (none)

8.1 Water TANK - old but in good condition still operates good.

8.6 TANK Pan - Re direct the drain pipe to correct connection for proper water disposal.

8.7 Tank Seismic Straps - Added some seismic straps to water heater

(Electrical)

9.3 Distribution Panel - install grommet on all the metallic holes where the wires came in for protection.

9.8 Lighting and Switch - Replace receptical & lights in the bedroom.

9.9 Visible Brand Wiring - wire remove and terminated behind the cabinet.

3.0 & 3.1 & 3.3 3.4 & 4.1 & 4.5 & 4.6

all address and fix. The tile in the bathroom

had signs of crack tile. Hard to get this exact tile we sealed it from future cracks. Very likely noticeable on the cracks.